



PRESS RELEASE

Velineon 380 Rotor & Rebuild Kit

The Traxxas Velineon 380 brushless motor can be rebuilt quickly and easily to restore like-new performance using the new Rebuild Kit (#3372) and Replacement Rotor (#3373). The rebuild kit includes precision 4X9mm ball bearings, shims, and 2x6mm flat-head screws with pre-applied thread lock. The replacement rotor is identical to the stock Velineon 380 rotor. High-strength, high-temperature Neodymium magnets and epoxy balancing ensure maximum power and smooth, high-rpm operation. Full installation instructions are included with the rebuild kit and replacement rotor, and both are compatible with all 1/16 VXL models.



3372 Velineon 380 Rebuild Kit



3373 Replacement Velineon 380 Rotor



Designed for use in all Traxxas
1/16 VXL brushless models

Traxxas Velineon 380 Rotor & Rebuild Kit Features

- Restores factory-new performance
- Easy installation with illustrated instructions
- Epoxy-balanced rotor for efficient high-rpm operation and high performance
- Rebuild kit includes precision shims and high-speed ball bearings
- Compatible with Velineon 380 motor (#3371) and all Traxxas 1/16 VXL brushless models.

Part #	UPC Number	Description	Retail Price
3372	2033433720	Rebuild kit, Velineon 380 (4x9x4mm ball bearings (2), 2x6mm CCS (with threadlock) (2), front shims (2)).....	\$10.00
3373	2033433730	Rotor, Velineon 380 motor	\$40.00